

GUANGDONG DETECTION CENTER OF MICROBIOLOGY

REPORT FOR ANALYSIS

Report №.

2020FM25653R01E

Name of Sample

Air sterilization humidifier

Applicant

Foshan Nanhai Keri Electronic Co.Ltd.

Test Type



Address: Building 66, No.100 Central Xian Lie Road, Guangzhou, China Postcode: 510070

Tel: +86 20 87137666

Fax : +86 20 87137668

Website : www.gddcm.com



GUANGDONG DETECTION CENTER OF MICROBIOLOGY

ANALYSIS REPORT FOR



此物

验检测

Report №.:2020FM25653R01E Verification Code: 06951487

Name of Sample	Air sterilization humidifier	Test Type	Entrustment Test		
Applicant	Foshan Nanhai Keri Electronic Co.Ltd.	Address	13th Keyun North Road, B Zone,Shishan Science park,Nanhai, Foshan City ,Guangdong ,China		
Sample Source	Submitted for Testing by the Applicant	Sample Quantity	Two Samples Submitted		
Spec and Lot № of Sample	KD001	State and Characteristic	Machine		
Sample Received Date	2020-09-04	Test Completion Date	2020-10-10		
Test Standard and Method	Refer to 0	GB 21551.3-2010 Aj	ppendix A		
Item Tested	Air virus elimination effect				
Grito Grico Gri	o Gritto Gritto Gritto Gritto Gritto	Gritto Gritto Gritto	Steiner Gride Gride Gride Gride Gride		
esting resting resting					
Gritco Gritco Gri	The test data of the sample(s) is attac	ched to the page(s) o	f this report.		
Test Conclusion					
Grido Grido Gri					
resting Testing Testing		Issu	ie Date: 2020-10-15		

Remarks Manufacturer: Foshan Nanhai Keri Electronic Co.Ltd.(provided by herapilicant)

Wuqiuyan **Editor:**

Verifier:

Là Sujuan

Approver: Xie Xiaobao

Page 2 of 4



GUANGDONG DETECTION CENTER OF MICROBIOLOGY

Report №.: 2020FM25653R011	Emice anice anice anic	anice anic	aniat aniat aniat	anice anice anice
Virus and host cell	作用时间 Action Time	试验序号 Serial Number	空气病毒含量 Air virus content (TCID ₅₀ /m ³)	Removal rate
H1N1 Influenza virus	smit Gmit Gmit Gmit	Grill Gril	2.44×10^{6}	and and a
	0 (CK)	2	2.44×10^{6}	
		3	2.44×10^{6}	
(A/PR/8/34) Host cell: MDCK	smic critic critic critic	Grill Gril	1.14×10^{2}	99.99
Testing Testing Testing Testing	2h	2	1.14×10^{2}	99.99
	contra restina restina restina	3	1.14×10^{2}	99.99

ANALYSIS AND TEST RESULT

Note: The natural decay of the microorganisms in the air has been eliminated.

(Blank below)

分析。

Remarks

To electrolyze tap water. After the sterilization module continuously operates for 30mins, Test was carried out in the $30m^3$ test chamber, and the working time was 2h.



Report №.: 2020FM25653R01E

Notice Items

- 1. The Test report is invalid if not affixed with Authorized Stamp of Test and Paging Seal.
- 2. The Test report is invalid without signature of verifier and approver.
- 3. The Test report is invalid if being supplemented, deleted or altered.
- 4. Without prior written permission, the report cannot be reproduced, except in full.
- Unless otherwise stated, the results shown in this test report refer only to the sample(s) submitted.
- 6. Any dispute of the report must be raised to the testing body within 15 days after the report is received, exceeding which the dispute will not be accepted.

ショーショー

- 7. For the tested sample(s) submitted by the applicant, the sample information in the test report is provided by the applicant and the laboratory is not responsible for its authenticity.
- This test report is for reference only to the applicant and does not have a proof of effect for others.